

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

**2009 Ford F150 4WD Flex Supercrew 4WD XLT 5.4L**

<b>VIN</b>	1FTPW14V29FA95017		
<b>Ext. Color</b>	Tan		
<b>Int. Color</b>	Gray	<b>Interior</b>	Cloth
<b>Mileage</b>	70,762 <b>Actual Miles</b>		
<b>Engine</b>	5.4L 8-Cylinder Gas		
<b>Transmission</b>	Automatic		



## Auction Data

<b>Sale Date</b>	To Be Announced		
<b>Run #</b>	To Be Announced	<b>Inv #</b>	0359
<b>Consignor</b>	GSA FLEET SERVICES		

## Declarations

<b>Warranty</b>	GSA Regular Terms
<b>Mileage</b>	70,762 <b>Actual Miles</b>
<b>Title</b>	Clear Title
<b>Announcements</b>	CROSS MEMBER DAMAGE ,

## Equipment

- 4 Wheel Drive
- Air Conditioning
- Trip Counter
- Alloy Wheels
- Towing Package
- Electric Mirrors
- Automatic Transmission
- Electronic Traction Control
- Cruise Control
- Tilt Steering Wheel
- Hard Top
- 8 Cylinder Gas
- Power Windows
- Dual Air Bag
- AM/FM CD
- Power Steering
- 6 Passenger
- Power Locks
- Anti Lock Brakes
- Keyless Entry
- Power Brakes

## Damage Descriptions (CR completed on 11/18/2014 by SKYLAR FICKLIN)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Front</b>									
1	Front Bumper	Chips	10 Or More						--
									--
2	Hood	Chips	10 Or More						--
									--
<b>Front Subtotal</b>				--	--	--	--	--	--
						--	--	--	--

# 2009 Ford F150 4WD Flex Supercrew 4WD XLT 5.4L

VIN: 1FTPW14V29FA95017

Inv#: 0359

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

## Interior

3	Carpeting	Dirty	Multiple Instances						--
4	Headlining	Dirty	Multiple Instances						--
5	Interior	Dirty	Multiple Instances						--
6	Seats	Dirty	Multiple Instances						--

### Interior Subtotal

--	--	--	--	--	--
		--	--	--	--

## Left

7	Left Bed Side	Dents W/ Paint Dmg	> 12 Inches						--
8	Left Rear Door	Scratched	> 12 Inches						--

### Left Subtotal

--	--	--	--	--	--
		--	--	--	--

## Mechanical

9	Air Conditioner	Checked - Ok	None						--
10	Engine	Checked - Ok	None						--
11	Transfer Case 4x4	Checked - Ok	None						--
12	Transmission	Checked - Ok	None						--

### Mechanical Subtotal

--	--	--	--	--	--
		--	--	--	--

## Rear

13	Tailgate	Dents W/ Paint Dmg	> 12 Inches						--
----	----------	--------------------	-------------	--	--	--	--	--	----

### Rear Subtotal

--	--	--	--	--	--
		--	--	--	--

## Right

14	Right Bed Side	Scratched	> 12 Inches						--
----	----------------	-----------	-------------	--	--	--	--	--	----

# 2009 Ford F150 4WD Flex Supercrew 4WD XLT 5.4L

VIN: 1FTPW14V29FA95017

Inv#: 0359

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
15	Right Front Door	Multiple Dents/Paint	3						--
16	Right Rear Door	Dents W/ Paint Dmg	7 To 8 Inches						--

## Right Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

## Structural

17	Center Cross Member	Bent	Other	--
				--

Comment: Brackets Have Dmg- Fail

## Structural Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

## Total

--	--	--	--	--	--
--	--	--	--	--	--

## Tires

Region	Brand	Size	Tread Depth
Left Front	FACTORY	/-	Average (Average)
Left Rear	FACTORY	/-	Average (Average)
Right Front	FACTORY	/-	Average (Average)
Right Rear	FACTORY	/-	Average (Average)
Spare	FACTORY	/-	Average (Average)

## Miscellaneous

Coolant level	OK
Interior odor	OK
Oil level	OK
Transmission fluid level	OK

# 2009 Ford F150 4WD Flex Supercrew 4WD XLT 5.4L

VIN: 1FTPW14V29FA95017

Inv#: 0359

## Images





## 2009 Ford F150 4WD Flex Supercrew 4WD XLT 5.4L

VIN: 1FTPW14V29FA95017

Inv#: 0359

